

1 Building constructions characteristics and mechanical properties of confined masonry walls
2 in San Miguel (Puno-Peru)

3

4 Tarque Nicola ^{(1)*}, Pancca-Calsin Erika ⁽²⁾

5 ¹ Pontificia Universidad Católica del Perú. GERDIS Research Group, Civil Engineering Division.

6 Av. Universitaria 1801, San Miguel, Lima, Peru. Email: sntarque@pucp.edu.pe

7 ² Universidad Peruana Unión. Autopista Héroes de la Guerra del Pacifico, Juliaca, Peru. Email:

8 erikapancca@upeu.edu.pe

9 * Corresponding author: sntarque@pucp.edu.pe

10

11 **ABSTRACT**

12 House self-construction and self-management are very common in different cities in Peru, which is
13 the case in several areas in the district of San Miguel (Puno). This is due to the lack of financial
14 resources to hire professionals to design and construct their houses. Therefore, many residents build
15 without technical guidance and materials without quality standards. As a result, the buildings in the
16 area have various construction pathologies that demonstrate their high seismic vulnerability, which
17 indicates that the guidelines established in the Peruvian Masonry Design Code NTE 070 are not
18 followed. Therefore, as a first step towards evaluating the seismic vulnerability of the houses in San
19 Miguel, it was decided to evaluate the construction pathologies and typologies by conducting a
20 survey. Subsequently, to characterize and evaluate the physical-mechanical properties of the
21 masonry walls, 24 piles and 24 small walls were built and tested. The materials tested were obtained
22 from the urban area of the same study place. According to the experimental tests, it was observed
23 that the axial compression and diagonal shear values of the prisms are lower than the minimum
24 values specified in the Peruvian Construction Code, and this would increase the seismic
25 vulnerability of the constructions. Therefore, many of the houses in the district could suffer
26 significant damage and even collapse in a seismic event.

27

28 **Keywords:** non-engineering buildings; construction pathologies; masonry prisms; experimental
29 tests, seismic vulnerability; damage survey, Puno

30

31 1. INTRODUCTION

32 In some Peruvian cities, there has been an exponential increase in population, consequently
33 increasing the need for housing. In addition, there is a lack of resources to acquire a finished house
34 or hire professionals to design and build confined masonry structures. As a result, many residents are
35 forced to build informally, that means, without technical supervision and with cheap materials of
36 questionable quality (Flores et al. 2019, Yacila et al. 2019, Blondet et al. 2006).

37 The confined masonry (CM) buildings are characterized by masonry walls (fired clay units) enclosed
38 with reinforced concrete (RC) elements along the four edges. These RC elements may avoid out-of-
39 plane failure and improve the shear in-plane behaviour of the walls. Unlike unreinforced masonry
40 buildings (URM), where kinematic failure modes may be analyzed (i.e. Micelli et al. 2016), CM
41 walls are more likely to fail in-plane. Also, some reseachers have studied the use of confine elements
42 to strength URM walls built with other unit types (Khan et al. 2021, San Bartolomé et al. 2009).

43 The CM walls (built with fired caly units) are the main structural elements that provide lateral
44 stiffness to the dwellings against the action of earthquakes and transfer the loads coming from the
45 slab to the foundation (Varela-Rivera et al. 2019, Marques and Lourenco 2019). An appropriate
46 density of CM walls in a structure and both directions allows the building to perform well in seismic
47 events. Therefore, it is necessary to know the constructive flaws of the walls, the characteristics and
48 mechanical properties of the masonry, the variability in the mortar thicknesses (Reddy et al. 2009),
49 and the quality of its materials to estimate the structural safety of the assembly. Based on data from
50 national censuses and annual measurements that CAPECO (2018) conducted on the formal housing
51 market, it is estimated that the percentage of informally built housing in Peru between 2007 and
52 2014 in Lima is 68.5%. In addition, it is inferred that the percentage of informal housing would be
53 equal to or greater than 70% in the rest of the country (Zavala et al. 2019).

54 Seismic vulnerability is represented by the susceptibility of a structure to suffer damage (Vatteri and
55 D'ayala 2021, Preciado et al. 2020, Ranjbaran and Kiyani 2017). Vulnerability reflects the lack of

56 strength of a building to earthquakes, as indicated by Bommer et al. (1998), and depends on the
57 building design characteristics, the quality of materials and the construction technique (Kuroiwa
58 2002).

59 Blondet et al. (2004) conducted a study on analyzing the seismic vulnerability of informal CM
60 dwellings in the Peruvian coastal area. It is determined that if a house is average but the quality of
61 construction is poor (e.g. use of low-quality materials), then the seismic vulnerability can be
62 assessed as high. Likewise, these houses are built in stages, depending on the inhabitants'
63 availability of economic resources. According to Sánchez et al. (2019), the progressive construction
64 and the use of low quality materials may infer in a high seismic vulnerability since there is not
65 engineering building planning for the future. Also, Hadzima-Nyarko et al. (2016), and Parammal and
66 D' Ayala (2021) studied the vulnerability of confined masonry buildings and agree that the seismic
67 capacity may decrease when there are more deficiencies in the construction (e.g. poor wall-column
68 connection, low wall density, unconfined walls, spacing of cross walls, etc). This is why houses with
69 severe structural, architectural and construction deficiencies make them vulnerable to natural
70 phenomena such as earthquakes (Ruiz-García and Negrete 2009, Sánchez et al. 2019, Zavala et al.
71 2019).

72 Vulnerability usually manifests itself through various pathologies that appear in buildings. Many
73 researchers have studied the seismic vulnerability of masonry buildings on a local and large scale
74 demonstrated the necessity for understanding the seismic behaviour of those buildings and their
75 relationship to their mechanical material properties (Ahmad et al. 2010, Blondet et al. 2006, Flores et
76 al. 2019, Hadzima-Nyarko et al. 2016, Lovón et al. 2018). González et al. (2008) understand
77 pathology as a systematic deficiency that occurs in most constructions because of the poor quality of
78 materials used in construction, construction errors that are not identified that way by the builders, the
79 lack of a culture of quality in the supervision, the lack of regulations and legislation in construction,
80 among others. Consequently, it is necessary to determine the quality of the CM constructions and the
81 properties of the materials that the houses are built with.

82 As in other cities in Peru, in the district of San Miguel in Puno, the application of construction
83 standards appears to be still incipient. Nevertheless, the population makes a considerable investment

84 in constructing their housing, even saving several years. Therefore, the houses must be safe in the
85 event of a seismic event.

86 Puno has gone through several experiences of earthquakes, such as those that occurred in 1928
87 (6.9*M_s*) and 2016 (6.3*M_w*), which caused damage to homes (making them uninhabitable) and even
88 caused collapses. Therefore, to predict the seismic response of residential masonry walls, it is
89 essential to study their physical-mechanical characteristics and properties (Quiroz et al., 2014).
90 Furthermore, to evaluate the mechanical behavior of a masonry wall, it is necessary to know its
91 mechanical properties through experimental tests (Perez-Gavilán et al. 2019, Almeida et al. 2014,
92 Binda et al., 2014). For this reason, this study evaluated the mechanical characteristics of piles and
93 walls built with typical bricks from the San Miguel area to verify whether they meet the
94 requirements of Peruvian standard NTE 070 (2006) and thus infer their seismic vulnerability.


95

96 **2. EVALUATION OF THE HOUSES**

97 **2.1. Surveys in the study area**

98 The study was carried out in the district of San Miguel, which belongs to the province of San Román
99 in the department of Puno and is home to approximately 65,500 people. Figure 1 shows the location
100 map of San Miguel at the national, departmental and provincial levels. In Puno, the buildings have
101 grown without specific planning due to the spontaneous union of neighbourhoods and urbanizations
102 in its surroundings. This uneven and disorganized growth had different consequences in several
103 aspects, such as the heterogeneity in the variety and uses of housing. Likewise, the lack of a political
104 organization and the lack of attention to basic needs and services forced the population of the
105 northern area to create the district of San Miguel in 2016. Approximately 12 340 out of 16 130
106 dwellings in San Miguel are made of clay brick (INEI 2018). In this research, 92 dwellings were
107 chosen to be evaluated and intended to represent the construction typology of the area.

108 Unfortunately, it was impossible to have a more significant number of surveys because many
109 villagers were afraid that this study was part of the local government's tax data update campaign.
110 Nevertheless, figure 2 shows some of the surveyed dwellings, where it can be noticed how these
111 dwellings grow without an adequate architectural order.



112

113

Figure 1. Location map of the district of San Miguel, Puno.

114



115



116



117

118

Figure 2. Some surveyed households in the district of San Miguel (Puno).

119

120

Fieldwork, office work and experimental trials were carried out. The fieldwork consisted in

121

obtaining information using survey sheets from one wall of the first level per dwelling. As shown in

122

Figure 3, the sheets consist of 2 pages whose format was divided into general data on the house,

123

structural characteristics and wall construction. The latter includes the evaluation of the masonry

124

unit (quality and aesthetics, dimensions and superficial condition), mortar construction joints

125 (thickness, quality and finish) and wall settlement (alignment, type of rigging, aesthetics, and finish).
 126 Additionally, existing pathologies were noted: unconfined walls, non-uniform mortar joint thickness,
 127 cracks in the walls, presence of salinity in the overlying walls, poor horizontal and vertical alignment
 128 of masonry units, cracks in columns and confining beams, efflorescence in walls, low-quality
 129 masonry units, poor mortar-unit interaction, cracks in the mortar, poor column-wall interaction, wall
 130 construction at different times, exposed steel, existence or not of seismic joints, among others.
 131 Moreover, observations, comments, construction schemes and photographs of masonry walls were
 132 also added to the file. Finally, the sheets were filled out by hand at the time of the home visit.
 133

FICHA DE ENCUESTA IN SITU Ficha N° 46

Evaluadora: Erika Leonor Pancca Calsin Fecha de encuesta: 15/09/2018

1. DATOS INFORMATIVOS:
 1.1 DATOS GENERALES DE LA UBICACIÓN DE LA EDIFICACIÓN Y/O VIVIENDA
 Región: **Puno** Provincia: **San Román** Distrito: **San Miguel** Barrio y/o otro: **Jr. 12 de Agosto**

2. DESCRIPCIÓN GENERAL DE LA EDIFICACIÓN:
 N° DE PISOS: 02 TIPO DE USO: FAMILIAR COMERCIAL
 SECUENCIA CONSTRUCTIVA: 1 NIVEL C/TIEMPO TODO A LA VEZ
 LA VIVIENDA ¿PRESENTA JUNTAS SÍSMICAS?: SÍ NO

3. ELEMENTO ESTRUCTURAL:
3.1 UNIDAD DE ALBAÑILERÍA
 MECANIZADO ARTESANAL BLOQUETAS

3.1.1 CALIDAD Y/O ESTÉTICA
 BUENO: Quemado uniforme en la mayoría de las unidades de albañilería.
 REGULAR: Quemado no uniforme en algunas unidades de albañilería.
 MALO: Quemado no uniforme en la mayoría de unidades de albañilería.

3.1.2 DIMENSIONES
 BUENO: Existe uniformidad en las dimensiones en mayor parte o totalidad del muro.
 REGULAR: Las dimensiones no presentan uniformidad en ciertos tramos del muro.
 MALO: Las dimensiones NO presentan uniformidad en mayor parte del muro.

3.1.3 ESTADO SUPERFICIAL
 BUENO: Existe un buen acabado superficial y el ladrillo no presenta eflorescencia.
 REGULAR: Algunos ladrillos no muestran un buen acabado superficial.
 MALO: No existe un buen acabado superficial y la mayoría de las unidades de albañilería presentan eflorescencia.

3.2. JUNTAS DE CONSTRUCCIÓN DE MORTERO
3.2.1 ESPESOR:cm
 BUENO: Las juntas se encuentran entre 1 y 1.5cm de espesor.
 REGULAR: Muros cuyas juntas son mayores de 1.5cm e inferiores a 3cm de espesor.
 MALO: Viviendas cuyos muros presenten juntas superiores a los 3cm de espesor.

3.2.2 CALIDAD
 BUENO: Existe buena adherencia entre la arena y el cemento, muestran un color uniforme.
 REGULAR: Existen zonas donde no existe buena adherencia entre la arena y cemento, es un poco más oscuro que lo normal.
 MALO: Se muestra un mortero pobre, no existe adherencia entre la arena y cemento, y el color es más oscuro que lo normal.


3.2.3 ACABADO
 BUENO: Mano de obra de buena calidad. El mortero es uniforme en todo el muro, no presenta tramos con cangrejeras o sobresalientes.
 REGULAR: En algunos tramos el mortero sobresale o presenta cangrejeras (regular calidad de mano de obra).
 MALO: El mortero no es uniforme, en mayor parte del muro se presentan zonas con cangrejeras o sobresalientes. Pésima calidad de mano de obra.

3.3. ASENTAMIENTO DEL MURO
3.3.1 ALINEAMIENTO
 BUENO: Verticalmente se encuentran a plomo, y existe una correcta alineación horizontal y vertical.
 REGULAR: Existen tramos en los que la alineación horizontal y vertical son deficientes, y verticalmente no están a plomo.
 MALO: A lo largo del muro, se observa que no se encuentran verticalmente a plomo y se muestra una deficiente alineación horizontal y vertical.

3.3.2 TIPO DE APAREJO
 SOGA
 CANTO
 CABEZA

3.3.3 ESTÉTICA
 BUENO: Los muros son homogéneos en su totalidad, y no existen grietas.
 REGULAR: Algunas partes del muro no son homogéneas, y existen algunas grietas.
 MALO: Muros NO homogéneos y hay presencia de grietas en mayor parte del muro.

3.3.4 ACABADO
 BUENO: El muro presenta un buen confinamiento, por los cuatro lados (vigas y columnas).
 REGULAR: El muro no llega a la altura de la losa (viga), sólo existe confinamiento por las columnas.
 MALO: No existe un confinamiento adecuado.



134
 135

Figure 3. Household survey sheets, in Spanish.


4. PATOLOGÍAS EXISTENTES:

- | | |
|---|--|
| <input type="checkbox"/> Muros sin viga solera | <input type="checkbox"/> Cangrejeras en vigas de confinamiento |
| <input type="checkbox"/> Muros sin confinar resistentes a sismo (pórticos) | <input type="checkbox"/> Eflorescencia en el muro. |
| <input checked="" type="checkbox"/> * Espesor de juntas de mortero no uniformes | <input type="checkbox"/> Eflorescencia en la parte inferior de muros |
| <input checked="" type="checkbox"/> * Grietas verticales y/o diagonales a lo largo del muro | <input checked="" type="checkbox"/> * Desprendimiento de capas o desconchado de ladrillos |
| <input checked="" type="checkbox"/> * Salinidad en sobrecimientos | <input checked="" type="checkbox"/> * Ladrillos de baja calidad por su apariencia |
| <input type="checkbox"/> Grietas verticales de regular tamaño | <input checked="" type="checkbox"/> * Desprendimiento de partículas o desconchado de mortero |
| <input type="checkbox"/> Grietas diagonales de regular tamaño | <input type="checkbox"/> Deficiente interacción ladrillo - mortero |
| <input type="checkbox"/> Mala calidad de arena en el mortero por su apariencia | <input type="checkbox"/> Cangrejeras en el mortero. |
| <input checked="" type="checkbox"/> * Deficiente alineación horizontal de los ladrillos | <input checked="" type="checkbox"/> * Deficiente interacción columna - muro mediante los dentados. |
| <input type="checkbox"/> Deficiente alineación vertical de ladrillos | <input type="checkbox"/> Construcción de muros en tiempos diferentes. |
| <input type="checkbox"/> Deficiente interacción muro - viga | <input type="checkbox"/> Construcción de columnas en tiempos diferentes. |
| <input checked="" type="checkbox"/> * Cangrejeras en las columnas de confinamiento | <input checked="" type="checkbox"/> * Aceros expuestos |
| <input type="checkbox"/> Otros: | |

OBSERVACIONES Y/O COMENTARIOS:

Presenta grieta vertical a lo largo de la parte central del muro del tipo escalonada y mixta. Se aprecia también excesivas juntas de mortero y unidades de arcilla de baja calidad. Presenta una deficiente interacción columnas - muro, debido a que no existen los dentados de 5cm. El concreto en la columna surge desde el sobrecimiento.

ESQUEMA DE LA FORMA CONSTRUCTIVA DE MUROS DE ALBAÑILERÍA (TRENZADO LADRILLO Y MORTERO):



FOTOGRAFÍAS:



Figure 3. (Continuation) Household survey sheets, in Spanish.

136

137

138

139 The desk work consisted of the analysis of the survey sheets. The information collected in the field

140 was processed in report forms for each dwelling. The surveyed dwellings' characteristics (structural,

141 constructive, pathologies and typologies) were grouped, and a database was created. Subsequently,

142 to characterize and evaluate the physical-mechanical properties of the masonry walls of the houses,

143 laboratory work was carried out, which consisted of building and testing piles and walls. Before this,

144 control tests (classificatory and non-classificatory) were carried out on the masonry units and the


145 mortar. The tested materials were obtained from the same study site.

146

147 **2.2. Construction typologies**

148 Confined masonry (CM) walls are composed of clay brick walls surrounded by reinforced concrete
 149 (RC) elements. Some walls may have only on the ground floor an RC plinth. Typically, the
 150 longitudinal steel bars of the RC elements are composed of four bars of $\Phi 1/2''$, with stirrups of $\Phi 1/4''$.
 151 Details of typical dimensions of CM walls and their CM elements are shown in Figure 4.

152



153

154 **Figure 4. Typical confined masonry wall's configuration.**

155

156 From the 92 houses evaluated, six typologies of walls were obtained, defined according to the
 157 thickness of the vertical (J.V.) and horizontal (J.H.) mortar joints. The three most predominant pairs
 158 (J.V. - J.H.) were selected to be characterized in the masonry prisms. Typology 01 (T1) with mortar
 159 thickness (J.V. and J.H.) of 20mm, typology 02 (T2) with a thickness of 30mm and typology 03 (T3)
 160 with a thickness of 40mm. These results are shown in Figure 5: T1 represents 25% of dwellings, T2
 161 represents 58% of dwellings, and T3 represents 12%. An additional typology was considered a
 162 reference standard (TP), with mortar thickness between 10 to 15mm as indicated in NTE 070 (2006).

163





Figure 5. Distribution of walls according to the thickness of their joints.

2.3. Masonry wall pathologies

Vulnerability usually manifests itself through various pathologies that appear in buildings, ranging from minor damage and inconvenience to the occupants to significant failures that can cause the collapse of the dwelling or part of it (Astorga and Rivero 2009). Figure 6 shows the different pathologies found in the studied dwellings. For example, Figures 6a and 6b show an inadequate connection of the masonry units with the confining element since both elements have cracks or separations. In addition, figures 6c and 6d show that some houses have cracks in their walls. These cracks usually appear when there are differential settlements in the foundation due to low-strength concrete or the deficient use of reinforcing steel in the confining elements (Mosqueira and Tarque 2005). Likewise, Figures 6e and 6f show mortar joint thicknesses more significant than 15 mm (value recommended by NTE 070).

Moreover, these thicknesses are not homogeneous. Figures 6g and 6h show walls with efflorescence damage, a crystalline deposit (saltpetre) generally white colour that develops in the masonry or on the surface of the concrete, which, if not repaired, can increase and weaken the wall (Sathiparan and Rumeshkumar 2018, Annila et al. 2018). Figures 6i and 6j show no confining beam for the wall, and the columns are short due to the existence of windows. Finally, Figures 6k and 6l show the poor quality of the workmanship used in the construction of many houses, which, according to Mosqueira and Tarque (2005), can cause a reduction of up to 40% in the shear strength of the walls.



189 **Figure 6. Existing pathologies in analyzed dwellings.**

190 Figure 7 shows the percentage of incidence of various pathologies observed, the most predominant
 191 being the construction of walls with non-uniform mortar joint thickness (95%), houses with exposed
 192 steel (92%), with efflorescence in the lower part of walls (64%), with poor vertical alignment of
 193 bricks (63%), with the presence of cracks in mortars (62%), with the existence of salinity in overlays
 194 (62%), with the poor horizontal alignment of bricks (61%), with lack of good brick-mortar
 195 interaction (62%), with lack of good brick-mortar interaction (62%), with the presence of cracks in
 196 the mortar (62%), with the existence of salinity in the overlay (62%), with the poor horizontal brick
 197 alignment (61%), with lack of good brick-mortar interaction (59%), with deficient column-wall
 198 interaction through notching (54%), with cracks in confining columns (53%), among others.

199




Figure 7. Existing pathologies in evaluated dwellings.

3. EXPERIMENTAL TESTS

A total of 100 control trials were performed on masonry units (20 samples of dimensional variation, 20 of warping tests, 20 of compressive strength tests, 20 of suction tests and 20 of absorption percentage tests) and 48 tests on prisms (24 of axial compression in piles and 24 of diagonal shear in walls). The masonry units (average dimensions $0.20m \times 0.10m \times 0.07m$) were obtained from the exact study location, handmade and produced by two different producers, here named as F1 and F2.

212 **3.1. Control tests on the units**

213 The objective of the tests was to classify and determine the properties of the masonry units used in
214 this study. The control trials included both classificatory and non-classificatory tests.

215

216 **3.1.1. Qualifying tests**

217 For the tests, two random groups of 10 masonry units were taken per producer (a total of 20). The
218 properties related to the classification of the masonry units, according to NTE 070 (2006), are the
219 dimensional variation, warping and compressive strength tests, which were performed according to
220 the NTP 399.613 Standard.

221 The percentage of dimensional variation defines the height of the mortar courses, since the greater
222 the variation in the heights of the units, the need arises to increase the joint mortar thickness beyond
223 what is strictly necessary to achieve good adhesion (Gallegos and Casabonne 2005). The standard
224 joint thickness should be around 10 *mm*. NTE 070 (2006) indicates that for every 3 *mm* increase in
225 joint thickness, the compressive strength of the masonry and shear strength decreases by 15%.

226 Therefore, it is essential to know the dimensional variation. The test was performed on 20 units (F1
227 and F2) and consisted in measuring with a millimetre graduated ruler the three dimensions of the
228 unit (length, width and height) from the midpoints of the edges that limit each face. The warpage is
229 used to determine how concave or convex a masonry unit is. Values greater than 2 *mm* of warpage
230 can cause horizontal mortar joints to have hollows, hence, a poor bond between the unit and mortar
231 and lower shear strength of the wall. A total of 20 units (F1 and F2) were tested. The test consisted
232 of placing the surface of the unit on a flat table. Then, a metal ruler was placed on the diagonal of the
233 seating surface to measure the most bending part (concave or convex) using a graduated wedge.

234 Gumaste et al. (2006) indicate that the compressive strength of the brick can contribute between 25
235 to 50% of the shear strength of masonry walls. Twenty bricks (F1 and F2) were tested. The
236 compressive strength of the brick was obtained by dividing the breaking load by the gross area of the
237 brick.

238

239

240 **3.1.2. Non-classificatory tests**

241 These tests are more related to the construction procedure of masonry walls (Manchego and Pari
242 2016). For the tests, two random groups of 10 masonry units were selected, one group for each
243 producer of F1 and F2 masonry units. The suction measures the initial water absorption rate from the
244 bearing face of the masonry unit, a significant property to achieve adequate contact between the
245 mortar and the unit. For the present study, all 20 samples (F1 and F2) were tested. This property was
246 calculated as the relation between the unit's dry weight and the unit's weight after having placed it
247 for one minute inside a tray with a constant height of 3 *mm* of water to fill the voids of the seating
248 face of the unit with water.

249 The absorption percentage was performed to determine the amount of water contained in a masonry
250 unit, calculated through the weight of the masonry unit in dry conditions and the weight in saturated
251 conditions (after being immersed in water for 24 hours). This property is essential because the higher
252 the absorption percentage, the more porous the unit is and, therefore, the less resistant to weathering
253 (San Bartolomé 2008).

254

255 **3.2. Tests on mortars**

256 The compressive strength of the mortar influences masonry strength. Then, significant variability in
257 mortar strength causes variability in masonry strength (Jessop and Langan 2005). Mortar is made of
258 a mixture of fine aggregate and binders, to which a certain amount of water is added to provide a
259 workable and adhesive mixture (Manchego and Pari 2016). The mortar specimens were obtained
260 from the same mixture used for the construction of the prisms. Twelve cubes of approximately 50
261 *mm* on each side were formed. They were cured with water for 28 days and then tested in axial
262 compression.

263

264 **3.3. Tests on masonry prisms**

265 Piles and walls (prisms) are used to calculate the axial compressive strength and diagonal shear
266 strength of clay masonry, respectively. The prisms have to represent the walls as well as possible, so
267 they should be exposed to similar conditions and have the same variables (unit type, mortar dosage,

268 joint mortar thickness, rigging, workmanship, etc.) as the walls. To characterize the behaviour of the
269 handmade masonry walls, 48 prisms (24 piers and 24 walls) were built. In these prisms, 4
270 construction typologies were represented, the 3 typologies (T1, T2 and T3) that best represent the
271 walls of the houses (joint mortar thickness and cement dosage: sand), and the standard typology (TP)
272 with the characteristics indicated by NTE 070 (2006). For each typology, 3 specimens were built,
273 and each group was for handmade masonry units of the two producers (called F1 and F2).
274 Depending on the typology, the piles were built with 3 or 4 courses (heights between 0.30 and 0.38
275 *m*) and the slenderness was between 2.5 and 4. According to the NTP 399.605 (2013), the pile
276 slenderness should be between 1.3 and 5.0.

277 The small walls (called also wallets) were between 6 and 7 courses. The approximate dimensions of
278 the wall's assemblies were 0.60 x 0.60 *m*, as suggested by the NTP 399.621 (2004). The ASTM
279 E519 (2021) standard suggests a minimum dimension of 1.20 x 1.20 *m*, but also permit walls with
280 less dimension if the testing equipment may not accommodate bigger walls. RILEM TC 76-LUM
281 (1994) considers small walls built with at least 4 courses and keeping as much as possible a squared
282 shape. Then, the adopted dimension here agrees with the revised standards.

283 The construction characteristics of the specimens of the standard typology (TP) were as follows:
284 joint mortar thickness between 10 to 15 *mm* and a mortar dosage of 1:4 (cement: sand). This
285 typology was built respecting the indications of NTE 070 (2006). Regarding typologies T1, T2 and
286 T3, these were built with a joint mortar thickness of 20*mm*, 30*mm* and 40*mm*, respectively, the three
287 of them with a mortar dosage of 1:7 (cement: sand), the dosage most commonly used in housing
288 construction in the study area. To analyze the influence of these variables, the following parameters
289 were kept constant: the type of rigging (head bond), which represents almost 95% of the walls of the
290 houses studied, the workmanship, the age of the specimens (28 days) and the testing technique.

291 Regarding the workmanship, the prisms were made by a local master builder to replicate the
292 construction reality as closely as possible. The construction procedure was as follows: before
293 construction, the units were wetted by immersing them in a bucket of water for one minute to avoid
294 too much water absorption of the mortar, prisms verticality was controlled with a plumb line and a

295 level, heights were controlled with a scantling (wooden ruler), the prisms were cured by watering
296 during the first 3 days as this is what is commonly done in the construction of informal dwellings.
297 The axial compressive tests and the diagonal compression tests were force-controlled due to
298 limitations in the laboratory. The load was applied trying to keep a rate velocity of 10 *kN/min*. Since
299 no LVDTs were placed on the samples to measure deformations, just the maximum strength in each
300 test was computed.

301


302 3.3.1. Masonry piles

303 Masonry piles are prisms composed of bricks laid one on top of the other and joined with mortar, as
304 shown in Figure 8. 28 days after their construction, the piles were tested in axial compression. Only
305 forces were measured, but deformation was not measured. This test made it possible to determine the
306 strength of the walls to vertical loads, whose stress depends on the quality of the units, mortar and
307 unit-mortar interaction.



309 **Figure 8. Masonry piles, a) samples, b) test set up**

310 Figure 9 shows that failure in the piles was the development of vertical cracks through the units and
311 mortar.



313 **Figure 9. Failure mode of the tested piles, a) TP, b) T1, c) T2, and d) T3.**

314 The average pile dimensions and maximum compressive loads recorded during the tests are detailed
315 in Table 1.

316

317 **Table 1.- Average pile dimensions by type and maximum supported load.**


Typology	Dimensions in <i>mm</i>			<i>P</i> _{max} (kN)
	Length	Width	Height	
TP	201	102	325	71.86
T1	201	104	348	74.42
T2	200	103	376	56.44
T3	200	102	292	61.62

318

319 3.3.2. Masonry walls

320 One of the most critical situations in which a wall can be subjected to shear is in the event of a
321 seismic effect, hence the importance of knowing the mechanical behaviour of the masonry under this
322 type of stress (Tena and Miranda 2003). The test to determine this behaviour consists in applying a
323 diagonal tension to a squared wall. Two steel loading shoes were used to apply the machine load to
324 the specimen (ASTM E-519 2021). Figure 10 shows the walls constructed in this research. The
325 construction process was similar to that of the piles. During the tests, only the acting forces were
326 measured, but not the deformation of the diagonals on the wall faces.

327




328

Figure 10. Masonry walls, a) samples, b) test set up

329

330 The wall failure mode was mostly by diagonal cracking and breaking bricks and mortar, as shown in
 331 Figure 11. The two wooden tables along two wall sides were placed to avoid the fall of the broken
 332 pieces, but they did not have interaction with the walls during the tests.



335 **Figure 11. Failure shape of the tested walls, a) TP, b) T1, c) T2, and d) T3.**

336

337 Table 2 shows the dimensions of the tested walls and the average maximum load values for each
 338 type.

339

340 **Table 2.- Average dimensions of the walls by type and maximum load capacity.**

Typology	Dimensions in <i>mm</i>			Pu (<i>KN</i>)
	Length	Width	Height	
TP	578	543	200	68.76
T1	548	610	200	56.35
T2	578	583	200	50.68
T3	630	632	200	39.67

341

342

343

344

345 4. RESULTS

346

347 4.1. Control tests (classificatory and non-classificatory)

348 From the results of the classification tests, F1 bricks are classified as Type IV according to their
349 dimensional variation of 3.41%, and F2 bricks as Type III with a dimensional variation value of
350 4.17% (NTE 070 2006). Standard ITINTEC 331.017 (1978) indicates that Type IV bricks are high
351 strength and durability, suitable for rigorous service conditions and subjected to moderate exposure
352 to the elements. Type III bricks are medium strength and durable, suitable for use in low exposure to
353 weathering conditions.

354 On the other hand, according to their warping, the masonry units of both producers F1 and F2 are
355 classified as Type V, according to NTE 070 (2006). The average values for F1 were 1.40 mm convex
356 and 1.20 mm concave, and F2 bricks were 1.40 mm convex and 1.50 mm concave. ITINTEC 331.017
357 (1978) states that Type V bricks are high strength and durability, suitable for use in very rigorous
358 service conditions, and can also be subjected to moderate exposure to weathering conditions in
359 contact with heavy rain, soil and water.

360 Regarding the characteristic strength to axial compression ($f'b$) of the masonry units, NTE 070
361 (2006) considers 4.90 MPa as the minimum value to be considered as type I brick. The F1 bricks do
362 not classify at this minimum since their $f'b$ was 4.61 MPa on average. On the other hand, F2 bricks
363 (6.16MPa) do classify as Type I. Type I are bricks with meagre strength and durability, which can
364 only be used under minimum requirements (1 or 2-story houses) and avoiding direct contact with
365 rain or soil, according to ITINTEC 331.017 (1978).

366 From the non-classifying tests, which are more related to construction procedures, the suction values
367 must be between 10 and 20 gr/200cm²-min. From the values achieved in the tests, none of the units
368 is in this range. Therefore, it is recommended to water the units before setting, since, otherwise,
369 adverse effects could be generated when the unit absorbs water from the mortar. Regarding the
370 absorption test, the masonry units had values lower than the maximum value of 22% indicated by
371 NTE 070 (2006). About the saturation coefficient, units with values greater than 0.85 are too porous
372 and, therefore not very durable (San Bartolomé 1994). According to the results of the test, the

373 masonry units do not exceed the limit, which means that they are durable and, since they have a low
374 absorption percentage, they could also be exposed to the outdoors.

375 Despite the fact that the results of the qualification tests could be good in some aspects, the structural
376 quality of the units is poor given their low $f'b$ value, whose result varies even from one producer to
377 another (F1 and F2).

378

379 **4.2. Compression tests on mortars**

380 To compare the quality of the mortar used to construct the masonry prisms, cubic specimens of
381 mortar with two different dosages were made and tested. For the 1:4 dosage (cement: sand), which
382 was used for the TP standard typology, a compressive strength ($f'c$) of 14.4 MPa was obtained. For
383 the 1:7 dosage commonly used for housing construction in San Miguel (T1, T2 and T3), an $f'c$ of 8.2
384 MPa was obtained (43% lower than TP). San Bartolomé (1994) mentions that the poor quality of the
385 mortar can influence the compressive strength of the masonry by 10%. Therefore, the compressive
386 strength of the mortar should be similar to that of the unit. This is to avoid its failure by crushing and
387 giving homogeneity to the masonry.

388

389 **4.3. Axial compression tests on piles**


390 The axial compressive strength (f_m) of the piles was calculated using the following equation:

$$391 \quad f_m = C * \frac{P_{\text{máx}}}{\text{área}}$$

392 where C represents the coefficient of correction for slenderness that varies according to the height of
393 the pile and P_{max} is the maximum load applied on the prism. The value of C in this study was 0.92
394 for TP and T1; 0.94 for T2; and 0.88 for T3. The characteristic strength to the axial compression of
395 the masonry (f_m) was obtained as the average value of the samples tested (by typology) minus one
396 times the standard deviation.

397 Figure 12 shows a summary of the 24 results obtained from the axial compressive strength tests on
398 masonry piles. As can be seen, the f_m values obtained for TP did not reach the recommended value
399 by NTE 070 for handmade bricks (3.40 MPa), even though an adequate mortar was used in this

400 typology. It can be pointed out that this typology is the closest to the value recommended by the
 401 Peruvian standard. The f_m results obtained for the other typologies (T1, T2 and T3) are lower than
 402 the minimum recommended value. Therefore, the poor construction quality of the masonry walls in
 403 San Miguel is demonstrated.




404

405 **Figure 12. Characteristic strength to axial compression in TP, T1, T2 and T3 piles.**

406

407 According to values obtained for typologies T1, T2 and T3, it can be deduced that the characteristic
 408 strength to axial compression in piles is inversely proportional to the joint mortar thickness; that is,
 409 as the mortar joint thickness increases, the axial compression strength decreases. As shown in Figure
 410 13, the f_m value of TP (thickness $e= 10\text{ mm}$ and mortar 1:4) is 90% of the standard f_m ; of T1 ($e= 20$
 411 mm), between 80 and 88% of the standard; of T2 ($e= 30\text{ mm}$), between 67 and 70% of the standard;
 412 and T3 ($e= 40\text{ mm}$), 68% of the minimum specified value in the standard. It is also indicated that the
 413 mortar used in TP had a compressive strength of 14.4 MPa , and in the others of 8.2 MPa .



414

415 **Figure 13. Variation of f_m according to TP, T1, T2 and T3 mortar joint thickness.**

416

417 **4.4. Diagonal compression tests on walls**


418 ASTM E-519 (2021) and the NTP 399.621 (2004) standards defines the test method for determining
419 the diagonal tensile strength (vm) assuming uniform shear stress conditions. In this case, the
420 diagonal tensile and shear strength are the same. These standards recommends the following
421 equation for evaluating the diagonal tensile (shear) strength:

422
$$vm = 0.707 * \frac{Pu}{An}$$

423 where Pu is the maximum force supported by the wall and An is the area of one side of the
424 specimen. The characteristic strength of the masonry to shear obtained from diagonal compression
425 wall tests ($v'm$) was obtained as the average value of the tested specimens (by typology) minus one
426 time the standard deviation.

427 It is important to mention that RILEM TC 76-LUM (1994) establishes that the stress state is not
428 uniform along the diagonal of the wall. Then, there are different equations to compute the tensile and
429 shear strength. The first is obtained as $0.5 Pu/An$, and the second as $0.88 Pu/An$ (Brignola et al. 2008).
430 As Crisci et al. (2020) mention, the tensile strength of masonry walls is lower than the one computed
431 with ASTM E-519 (2021), while the pure shear strength is higher.

432 Figure 14 shows the results obtained from the diagonal tensile strength tests on masonry walls
433 following the ASTM E-519 (2021) and NTP 399.621 (2004), no deformation gauges were used.
434 Even though the TP walls were built with a good quality mortar and respecting the thickness of the
435 joints, their $v'm$ value did not reach the minimum value recommended by NTE 070 (2006) for
436 handmade bricks ($0.50 MPa$). The diagonal tensile (shear) strength values of the other typologies are
437 well below the recommended minimum. This situation is of concern since $v'm$ is a direct value to
438 evaluate the seismic capacity of confined masonry housing. It is essential to mention that the $v'm$ for
439 industrial bricks is $0.80 MPa$ according to the standard. In case to use RILEM TC 76-LUM (1994)
440 standard, the computed tensile strengths will be less than the ones reported in Figure 14.




441

442 **Figure 14. Diagonal tensile (shear) strength characteristic for TP, T1, T2 and T3 walls**

443 **computed with ASTM E-519 (2021) and NTP 399.621 (2004).**

444

445 Similar to piles, it can be deduced that the characteristic strength to diagonal shear in walls is
 446 inversely proportional to the thickness of the mortar joint; that is, as the thickness of the joint mortar
 447 increases, the diagonal shear strength decreases. Figure 15 shows that the $v'm$ value of TP ($e= 10$
 448 mm) is around 77% of the $v'm$ of the standard; of T1 ($e= 20 mm$) 60% of the standard; of T2 ($e= 30$
 449 mm) between 54 and 58% of the standard; and T3 ($e= 40 mm$), between 38 and 42% of the minimum
 450 value specified in the standard.



451

452 **Figure 15. Variation of $v'm$ according to TP, T1, T2 and T3 mortar joint thickness.**

453

454 **5. CONCLUSIONS**

455 Of all the surveyed houses, 25% have walls with joint thicknesses of 20 mm , 58% with 30 mm , 12%
 456 with 40 mm , and 5% variable. In addition, the inhabitants use handmade bricks for construction. The
 457 10 most common construction problems in these houses are walls with non-uniform mortar joint

458 thickness, exposed steel, efflorescence in the lower part of walls, poor horizontal and vertical
459 alignment of bricks, presence of hollowness in mortar, salinity in overlays, lack of good brick-mortar
460 interaction, deficient column-wall interaction through notching, and hollowness in confining
461 elements. This demonstrates the lack of professional counselling during the design and construction
462 of housing in San Miguel and Puno in general.

463 From the results of axial compression in piles and diagonal compression in walls, it can be
464 concluded that the strength values are inversely proportional to the thickness of the mortar joints;
465 this means that the greater the thickness of the joint, the lower the strength value of the masonry. In
466 axial compression, masonry built with handmade bricks and joint thicknesses of 20, 30 or 40 *mm*
467 reduces its axial strength by 15, 32 and 35%, concerning the minimum value of 3.40 *MPa* specified
468 by the Peruvian standard. For diagonal compression, the same joints show a shear strength reduction
469 in the walls of 40, 45 and 60%, concerning the standard's minimum value of 0.50 *MPa*. Although in
470 masonry with a joint thickness of 10 *mm* and a mortar with a cement:sand ratio of 1:4, the masonry
471 strength values are below the minimum values recommended by the standard. In addition to the
472 construction problems identified during the surveys, it can be deduced that the houses in San Miguel
473 have a high seismic vulnerability and could fail and even collapse in case of an earthquake. These
474 results demonstrate the high seismic vulnerability of buildings in San Miguel and the urgent need to
475 implement training campaigns for the proper construction of seismic-resistant housing, study
476 massive forms of seismic reinforcement, and improvement of existing housing, thus mitigating the
477 seismic risk in Puno.

478

479 **ACKNOWLEDGMENTS**

480 The authors express their gratitude to Eng. Herson Pari, Eng. Ruben Sosa and Eng. Holger Lovon
481 for their support during the tests at the Universidad Peruana Unión, Juliaca.

482

483

484

485

486 **REFERENCES**

- 487 • Ahmad, N., Crowley, H., Pinho, R., Ali, Q. (2010). "Displacement-based earthquake loss
488 assessment of masonry buildings in Mansehra city, Pakistan". *Journal of Earthquake*
489 *Engineering*, 14 (S1), 1-37. <https://doi.org/10.1080/13632461003651794>
- 490 • Almeida, C., Guedes, J., Arêde, A., and Costa, A. (2014). "Shear-compressive experimental
491 behaviour of one-leaf stone masonry walls in north of Portugal". *Proceedings of the Second*
492 *European Conference on Earthquake Engineering and Seismology*, Estambul, Turkey.
- 493 • Annila, P., Lahdensivu, J., Suonketo, J., Pentti, M., and Vinha, J. (2018). "Need to repair
494 moisture- and mould damage in different structures in finnish public buildings". *Journal of*
495 *Building Engineering*, 16, 72-78, <https://doi.org/10.1016/j.jobbe.2017.12.010>.
- 496 • ASTM E519 / E519M-21, Standard Test Method for Diagonal Tension (Shear) in Masonry
497 Assemblages, ASTM International, West Conshohocken, PA, 2021, www.astm.org.
- 498 • Astorga, A. and Rivero, P. (2009). "Patologías en las Edificaciones". *Centro de Investigación en*
499 *Gestión Integral de Riesgos*, Venezuela.
- 500 • Binda, L., Baronio, G., Penazzi, D., Palma, M., and Tiraboschi, C. (2014). "Caratterizzazione Di
501 Murature in Pietra in Zona Sismica: Data-base Sulle Sezioni Murarie e Indagini Sui Materiali".
502 *Proceedings of the 9th Convegno Nazionale Ingegneria Sismica*, Torino, Italy.
- 503 • Blondet, M., Tarque, N., and Velasquez, J. (2006). "Seismic risk assessment of informally built
504 confined masonry dwellings in Peru". *Proceedings of the First European Conference on*
505 *Earthquake Engineering and Seismology*, 627.
- 506 • Blondet, M., Dueñas, M., Loaiza, C., and Flores, R. (2004). "Seismic vulnerability of informal
507 construction dwellings in Lima, Perú: preliminary diagnosis". *Proceedings of the 13th World*
508 *Conference on Earthquake Engineering*, 2122.
- 509 • Bommer, J., Salazar, W., and Samayoa, R. (1998). "Riesgo sísmico en la Región Metropolitana
510 de San Salvador". Programa Salvadoreño de Investigación sobre desarrollo y medio ambiente,
511 San Salvador.

- 512 • Brignola, A., Frumento, S., Lagomarsino, S., and Podestà, S. (2008). “Identification of shear
513 parameters of masonry panels through the in-situ diagonal compression test”. *International*
514 *Journal of Architectural Heritage*, 3 (1), 52–73, <https://doi.org/10.1080/15583050802138634>.
- 515 • Cámara Peruana de la Construcción CAPECO (2018). “Construyendo formalidad”.
516 Construcción e Industria, Julio-Agosto de 2018.
- 517 • Crisci, G., Ceroni, F., and Lignola, G. P. (2020). “Comparison between Design Formulations
518 and Numerical Results for In-Plane FRCM-Strengthened Masonry Walls”. *Applied Sciences*, 10
519 (14), 4998, <https://doi.org/10.3390/app10144998>.
- 520 • E.070 (2006). “Reglamento Nacional de Edificaciones: Albañilería”. Ministerio de Vivienda,
521 Construcción y Saneamiento-SENCICO, Lima, Perú.
- 522 • Flores, E., Diaz, M., and Zavala, C. (2019). “Development of fragility function for typologies of
523 confined masonry dwelling in Metropolitan Lima and Callao cities”. *Earthquake engineering*
524 *design and evaluation*, 29 (2), 151-158, <http://dx.doi.org/10.21754/tecnica.v29i2.717>.
- 525 • Gallegos, H. and Casabonne, C. (2005). “Albañilería Estructural”. Lima - Perú: Fondo Editorial
526 de la Pontificia Universidad Católica del Perú.
- 527 • González, R., Aguilar, J., and Gómez, C. (2008). “Patologías constructivas de viviendas en
528 Chiapas”. *Lacandonia revista de Ciencias de la Universidad de Ciencias y Artes de Chiapas*, 2
529 (1), 73-86.
- 530 • Gumaste, K., Nanjunda, K., Venkatarama, B., and Jagadish, K. (2006). “Strength and elasticity
531 of brick masonry prisms and wallets under compression”. *Material and Structures*, 40(2) 241-
532 253, <https://doi.org/10.1617/s11527-006-9141-9>.
- 533 • Hadzima-Nyarko, M., Pavico, G., and Lesic, M. (2016). “Seismic vulnerability of old confined
534 masonry buildings in Osijek, Croatia”. *Earthquakes and Structures*, 11 (4), 629 – 648,
535 <https://doi.org/10.12989/eas.2016.11.4.629> .
- 536 • INEI, Instituto Nacional de Estadística e Informática. (2018). “Perú: Crecimiento y distribución
537 de la población total, 2017”. Lima, Perú: Censos nacionales 2017: XII de población, VII de
538 vivienda y III de comunidades indígenas.

- 539 • Jessop, E. and Langan, B. (2005). “Influence of mortar cube strength variability on the measured
540 compressive and flexural strengths of clay masonry prisms”. *Proceedings of the Vth*
541 *International Brick Masonry Conference*, 2, 163 - 170.
- 542 • Khan, F. Z., Ahmad, M. E. and Ahmad, N. (2021). “Shake table testing of confined adobe
543 masonry structures”. *Earthquakes and Structures*, 20(2), 149-160.
544 <https://doi.org/10.12989/eas.2021.20.2.149>
- 545 • Kuroiwa, J. (2002). “Reducción de desastres: Viviendo en armonía con la naturaleza”. Lima,
546 Perú: Programa de las Naciones Unidas para el Desarrollo (PNUD).
- 547 • Lovon, H., Tarque, N., Silva, V., and Yepes-Estrada, C. (2018). “Development of Fragility
548 Curves for Confined Masonry Buildings in Lima, Peru”. *Earthquake Spectra*, 34 (3),
549 <https://doi.org/10.1193/090517EQS174M>.
- 550 • Manchego, J. and Pari, S. (2016). “Análisis experimental de muros de albañilería confinada en
551 viviendas de baja altura en Lima, Perú”. M.S. thesis, Pontificia Universidad Católica del Perú,
552 Lima, Perú.
- 553 • Marques, R. and Lourenço, P. (2019). “Structural behaviour and design rules of confined
554 masonry walls: Review and proposals”. *Construction and Building Materials*, 217, 137-155,
555 <https://doi.org/10.1016/j.conbuildmat.2019.04.266>.
- 556 • Micelli, F., Cascardi, A., and Marsano, M. (2016). “Seismic strengthening of a theatre masonry
557 building by using active FRP wires”. In *Brick and Block Masonry: Proceedings of the 16th*
558 *International Brick and Block Masonry Conference* (pp. 753-761). Padova, Italy: CRC Press,
559 <https://doi.org/10.1201/b21889>.
- 560 • Mosqueira, M. and Tarque, N. (2005). “Recomendaciones técnicas para mejorar la seguridad
561 sísmica de viviendas de albañilería confinada de la Costa Peruana”. M.S. thesis, Pontificia
562 Universidad Católica del Perú, Lima, Perú.
- 563 • NTP 399.605 (2013), Norma Técnica Peruana. “Unidades de albañilería. Método de ensayo para
564 la determinación de la resistencia en compresión de prismas de albañilería”.

- 565 • NTP 399.613 (2005), Norma Técnica Peruana. “Unidades de albañilería. Métodos de muestreo y
566 ensayo de ladrillos de arcilla usados en albañilería”.
- 567 • NTP 399.621 (2004), Norma Técnica Peruana. “Unidades de albañilería. Método de ensayo de
568 compresión diagonal en muretes de albañilería”.
- 569 • Parammal Vatteri, A. and D’Ayala, D. (2021). “Classification and seismic fragility assessment
570 of confined masonry school buildings”. *Bulletin of Earthquake Engineering*, 19, 2213–2263,
571 <https://doi.org/10.1007/s10518-021-01061-9>.
- 572 • Perez-Gavilan, J., Flores, L., and Alcocer, M. (2019). “An Experimental Study of Confined
573 Masonry Walls with Varying Aspect Ratios”. *Earthquake Spectra*, 31, 945-968,
574 <https://doi.org/10.1193/090712EQS284M>.
- 575 • Preciado, A., Ramirez, A., Santos, J., and Rodriguez, O. (2020). “Seismic vulnerability
576 assessment and reduction at a territorial scale on masonry and adobe housing by rapid
577 vulnerability indicators: the case of Tlajomulco, Mexico”. *International Journal of Disaster
578 Risk Reduction*, 44 (101425), <https://doi.org/10.1016/j.ijdr.2019.101425>.
- 579 • Quiroz, L., Maruyama, Y., and Zavala, C. (2014). “Cyclic behavior of Peruvian confined
580 masonry walls and calibration of numerical model using genetic algorithms”. *Engineering
581 Structures*, 75, 561-756, <https://doi.org/10.1016/j.engstruct.2014.06.035>.
- 582 • Ranjbaran, F. and Kiyani, A. (2017). “Seismic vulnerability assessment of confined masonry
583 buildings based on ESDOF”. *Earthquakes and Structures*, 12 (5), 489-499,
584 <https://doi.org/10.12989/eas.2017.12.5.489>.
- 585 • Reddy, B., Lal, R., and Rao, K. (2009). “Influence of Joint Thickness and Mortar-Block Elastic
586 Properties on the Strength and Stresses Developed in Soil-Cement Block Masonry”. *Journal of
587 Materials in Civil Engineering*, 21(10), 535-542, [https://doi.org/10.1061/\(ASCE\)0899-
588 1561\(2009\)21:10\(535\)](https://doi.org/10.1061/(ASCE)0899-1561(2009)21:10(535)).
- 589 • RILEM TC. 1994. 76-LUM. Diagonal tensile strength tests of small wall specimens, 1991. In
590 RILEM, Recommendations for the Testing and Use of Construction Materials. London: E&
591 FN SPON, 488–489.

- 592 • Ruiz-García, J. and Negrete, M. (2009). “Drift-based fragility assessment of confined masonry
593 walls in seismic zones”. *Engineering Structures*, 31 (1), 170-181,
594 <https://doi.org/10.1016/j.engstruct.2008.08.010>.
- 595 • San Bartolomé, A. (1994). “Construcciones de Albañilería”. Fondo Editorial de la Pontificia
596 Universidad Católica del Perú, Lima, Perú.
- 597 • San Bartolomé, Á. (2008). “Comentarios a la Norma E.070 ALBAÑILERÍA”. SENCICO, Lima
598 - Perú.
- 599 • San Bartolomé, Á., Delgado, E., and Quiun, D. (2009). “Seismic Behaviour of Two Story Model
600 of Confined Adobe Masonry”. *Proceedings of the Eleventh Canadian Masonry
601 Conference*. Toronto, Canada.
- 602 • Sánchez, V. M., González, R., Castañeda, G., García, C. M., and Aguilar, J. A. (2019).
603 “Characterization of pathologies in housing structures. A case study in the city of Tuxtla
604 Gutierrez, Chiapas, Mexico”. *Journal of Building Engineering*, 22, 539–548,
605 <https://doi.org/10.1016/j.jobe.2019.01.014>.
- 606 • Sathiparan, N. and Rumeskumar, U. (2018). “Effect of moisture condition on mechanical
607 behavior of low strength brick masonry”. *Journal of Building Engineering*, 17, 23-31,
608 <https://doi.org/10.1016/j.jobe.2018.01.015>.
- 609 • Tena, A. and Miranda, E. (2003). “Comportamiento mecánico de la mampostería”.
610 Edificaciones de mampostería para vivienda. Fundación ICA, 4, 103-132.
- 611 • Varela-Rivera, J., Fernandez-Baqueiro, L., Gamboa-Villegas, J., Prieto-Coyoc, A., and Moreno-
612 Herrera, J. (2019). “Flexural Behavior of Confined Masonry Walls Subjected to In-Plane Lateral
613 Loads”. *Earthquake Spectra*, 35 (1), 405-422, <https://doi.org/10.1193/112017EQS239M>.
- 614 • Vatteri, A. and D’Ayala, D. (2021). “Classification and seismic fragility assessment of confined
615 masonry school buildings”. *Bulletin of Earthquake Engineering*, 19, 2213-2263,
616 <https://doi.org/10.1007/s10518-021-01061-9>.

- 617 • Yacila, J., Salsavilca, J., Tarque, N., and Camata, G. (2019). “Experimental assessment of
618 confined masonry walls retrofitted with SRG under lateral cyclic loads”. *Engineering Structures*,
619 199, 109555, <https://doi.org/10.1016/j.engstruct.2019.109555>.
- 620 • Zavala, C., Diaz, M., Flores, E., and Cardenas L. (2019). “Damage limit states for confined
621 masonry walls based on experimental test”. *Journal TECNIA*, 29 (2), 135 – 141,
622 <https://doi.org/10.21754/tecnica.v29i2.715>.